

Albion-Sheridan

Activities

1) Inspect septic system. The location is marked with a stake. I think I will meet you out there so we can look at a couple of other things too. Mr. Praeter wants us to move a ridge of dirt. We flagged it last summer so hopefully those are still there also.

Wednesday We have arranged for a septic system company to meet you at the site at 1pm on ~~Monday~~. Mr. Praeter has wanted us to inspect this for quite some time. He is concerned that we damaged it during grading activities. However, we don't know it's original condition (it probably dates back to the 1950's). So, if he comes out, we have to get back to EPA, blah, blah, we have no authority, we're just doing our job. etc.

The septic system companies name is "Carr Brothers". Phone 531-3058

2) We also have to repair the fence. I've attached a map of the locations where it is damaged. I know you have seen "the hole". On the east side of the fence, it looks like someone cut the brackets holding the fence to the poles. One can easily pick up the mesh and slide under the fence. So, we need to wire those back onto the poles. It's kind of subtle but if I'm out there, the two of us should be able to find it.

The MDNR is going out to test pit so we can leave the water tanks and decon pad alone. They had asked if they could use them and Leah (U.S. EPA) said yes.

Liz (ext 404)



home phone 795-2335 (not after 9 pm please, we're running on empty!)

I'd like to leave from my house in the morning. When do you want to meet on-site??

US EPA RECORDS CENTER REGION 5




471089



LEGEND

- APPROXIMATE LANDFILL BOUNDARY (DASHED PORTIONS INDICATE THE SURVEY GRID BOUNDARY)
- PROPERTY BOUNDARY
- UNPAVED ROAD
- INTERMITTENT STREAM
- RAILROAD TRACK
- FENCE LINE
- TOPOGRAPHIC CONTOUR (10' INTERVAL)
- TOPOGRAPHIC CONTOUR (2' INTERVAL)



ALB-TOPO
LVP120693

FIGURE 3 SITE TOPOGRAPHY

ALBION-SHERIDAN TOWNSHIP LANDFILL
ALBION, MICHIGAN

DECEMBER, 1993

04011.03